

**PORT OF SUNDERLAND**

**NOTICE TO MARINERS**

**ENGLAND NORTH EAST COAST**

**LIGHTED BUOY MISSING FROM STATION**

**Ref. No. 23 of 2017**

**NOTICE IS HEREBY GIVEN** that due to recent sea conditions, the lighted buoy (Qk Fl R / Can R) marking the unfinished seaward end of New South Pier in position 54° 55.176' N 01° 21.157' W is missing from station.

A further Notice will be issued when the buoy has been reinstated.

Additional information can be obtained from Local Port Services, Port Control, Sunderland, on Marine VHF Channel 14 or by telephoning 0191 514 2752.

**CAPTAIN AK ULLAH**

Harbour Master

Port of Sunderland,  
Capstan House,  
Greenwells Quay,  
South Docks,  
Barrack Street,  
Sunderland,  
SR1 2BU.

Dated the 2nd day of December, 2017.